



## Roof Evaluation - Various City Facilities

### Recycling Center

Location: 2222 Oakton Year Built: 1990 Rehabbed: N/A Overall rating: Fair

**Current condition:** Per observation, the coping and flashing appeared to be in good condition. However, vegetation was present and this needs to be removed, to prevent further growth and existence of unwanted material.

**Recommended Strategy:** Maintenance



Key:  Area where vegetation was located.

**Core results:**

EPDM ballasted  
2" Polyisocyanurate  
Metal deck



## Roof Evaluation - Various City Facilities

